



SKULLERZ® 8955 // 8965

USER INFORMATION

USAGE: This bump cap does not provide protection against effects of falling/thrown objects or moving suspended loads and should not be used instead of an industrial safety helmet as specified in EN 397 or ANSI Z89. Bump Cap is made to absorb energy of a blow by partial destruction or damage to shell. Though such damage may not be readily apparent, any bump cap subjected to severe impact should be replaced. For adequate protection, cap must fit or be adjusted to the size of user's head. Do not modify or remove original component parts or adapt for the purpose of fitting attachments unless recommended by the manufacturer. Do not apply paint, solvents, adhesives or self-adhesive labels unless instructed by the manufacturer.

PROPER WEARING: For proper protection this bump cap must be worn with the peak facing forward. Place the cap on the head so that it sits down on to the top of the head, tilted back so that the peak does not obstruct the wearer's vision.

INSPECTION AND CARE: This bump cap's useful life is affected by many factors including: cold, heat, chemicals, sunlight and misuse. It should be examined daily for obvious signs of cracking, brittleness or damage. The production date is marked on the shell of each bump cap. Under normal circumstances this bump cap should offer adequate protection for 5 years. The shell should be cleaned/disinfected by wiping with a cloth moistened with a weak mild detergent solution and allowed to air dry. No strong or abrasive chemicals should be used. If the bump cap cannot be cleaned by this method it should be replaced. Follow instructions on the interior label for care of the fabric cover. When not in use the bump cap should be stored out of direct sunlight and not in contact with any chemicals or liquids. Care should be taken to avoid dropping the bump cap.

WARNINGS: When worn correctly this bump cap will restrict upward vision, while wearing the cap tilted too far back will significantly reduce the level of protection provided. As required by European Health and Safety requirements, the user is advised that when the bump cap is in contact with the user's skin, it may cause allergic reactions to susceptible individuals. If this is the case the wearer should remove the bump cap and consult a physician. None of the materials used in the construction of this bump cap are known to adversely affect wearer hygiene or health.

PROPER TRANSPORTATION: When transporting the bump cap use packaging that will minimize contact with direct sunlight, any chemicals or liquids, and extreme temperatures. The packaging should also keep the bump cap from excess outside force or pressure which could negatively impact the bump cap's performance.

HARMONIZED STANDARD: Complies with EN 812:2012

RISKS THIS BUMP CAP IS DESIGNED TO PROTECT AGAINST:

EU Directive 89/686/ECC, Annex II	Clauses of this European Standard
1.2.1 Absence of risks and other inherent nuisance factors	4.6, 5.1.3, 5.2.2, 5.2.3
1.3.1 Adaptation to user's morphology	4.5
1.3.2 Lightness and design strength	5.1.1, 5.1.2, 5.2.1
1.4 Information supplied by the manufacturer	7
2.2 PPE enclosing the parts of the body to be protected	4.2, 4.3
2.4 PPE subject to aging	7.2.3 e)
2.12 PPE bearing one or more identification or recognition marks directly or indirectly relating to health and safety	7
3.1.1 Impact caused by falling or projecting objects and collision parts of the body with an obstacle	5.1.1, 5.1.2

EU DECLARATION OF CONFORMITY CAN BE FOUND AT:
www.ergodyne.com

MANUFACTURER

Ergodyne
1021 Bandana Boulevard East, Suite 220
Saint Paul, MN, USA 55108
+1.800.225.8238

NOTIFIED BODY

BSI Group
Kitemark Court, Davy Avenue
Knowlhill, Milton Keynes
MK5 8PP, United Kingdom

AUTHORIZED EU REP

David Harrison
Brooke House
Tithebarn Lane
Preston PR31BH, United Kingdom
+441995600623